

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, KEINATH-68S96W/4NWNE

Location ID: 334152

Date: 2/27/2024



Wellheads – Photo #09621



Separators/Gas Meters – Photo #09622

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, KEINATH-68S96W/4NWNE

Location ID: 334152

Date: 2/27/2024



**Tank Battery/Tank Missing Labeling – Photo #09623**