

Operator: Crestone Peak Resources
Location Name: GEIST-63N67W 32NENW
Loc ID: 336315
Inspection: 715400006



Exhibit A



Exhibit B

CA: Weed debris at wellhead. Comply with Rule 606.

CA Resolution: Weed debris has been removed to comply with Rule 606.