

Operator: Highpoint Resources

Location Name: Anschutz Equus Farms 4-62-9_10 North

Loc ID: 433642

Inspection: 713900397



Exhibit A

CA: Wattle in the Northeast corner of the facility has degraded and is no longer functioning as a stormwater BMP and is now considered debris. Replace or remove the BMP per Rule 606.

CA Resolution: Wattle has been installed to comply with Rule 606.