

Inspection Photos

Loc: 324809

Operator: WESTERN OPERATING COMPANY

Inspection Date: 2/27/2024

County: KIOWA



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the access road toward the location.



Inspection Photos



February 27, 2024
+38.420635,-102.444324

Photo 2. Facing northeast towards the tank battery. The wind sock for H2s needs to be replaced.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324809 | Date: 2/27/2024

Inspection Photos



Photo 3. Facing southeast at the wellsite.



Inspection Photos



Photo 4. Facing east. There are two steel tanks that are unused that need to be removed along with various parts by the power pole.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324809 | Date: 2/27/2024