

# Inspection Photos

Loc: 324792

Operator: WESTERN OPERATING COMPANY

Inspection Date: 2/27/2024

County: KIOWA



**COLORADO**  
**Energy & Carbon Management**  
**Commission**  
Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the location. There are weed debris along the fence that will need to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 324792 | Date: 2/27/2024

## Inspection Photos



**Photo 2.** This tank appears to be unused and needs to be removed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Loc: 324792 | Date: 2/27/2024



## Inspection Photos



**Photo 3.** Facing northeast at the backside of the tank battery. The secondary containment at the red arrow has tipped over.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc: 324792 | Date: 2/27/2024