

Inspection Photos
Location Name: EHRLICH-66N64W/7NWSW
Location #: 322987



Photo #1
Ehrlich #1 (123-12382) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: stub-plug



Photo #2
Ehrlich #1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: stub-plug
Site safety signage



Inspection Photos

Location Name: EHRlich-66N64W/7NWSW
Location #: 322987



Photo #3
Ehrlich #1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: stub-plug
Wellsite entrance
prior photo




Photo #4
Ehrlich #1 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: stub-plug
JSA: 2024-02-28



Inspection Photos

Location Name: EHRLICH-66N64W/7NWSW

Location #: 322987



Photo #5

Ehrlich #1 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: stub-plug

Battery sign

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources