

**Operator: Civitas North**  
**Location Name: Rothe 12-14-8-61**  
**Loc ID: 424216**  
**Inspection: 709100217**



Exhibit A



**Exhibit B**

**CA:** Pipe located on site not securely fastened to prevent leaks. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition, per Rule 608.e.

**CA Resolution:** Pipes have been repaired to comply with Rule 608.e.