

Inspection Photos
Location Name: AMIGO-66N64W/17NWNE
Location #: 330135



Photo #1
Amigo 17-12 (123-18484) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 15 yds.



Photo #2
Amigo 17-12, Gulley 17-15, Uhrich 17-21 ;
Plugged & Abandoned | PA
Battery site
Abandoned: ALL Equipment Removed

