

Final Reclamation Inspection

February 22nd, 2024

Operator: Logos Operating LLC - 10679

Location ID: 312075

Inspection Document #: 714000486

La Plata County, CO

Township: SESE 7 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: 33-9N33N9W 7SESE
Location ID: 312075

2/22/24
+37.113650,-107.862447
24° NE




Photo 1. View of the disturbance facing center from the entrance. Note: disturbance is shared with the Logos Operating Bondad 33-9 17 gas well.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07146, 09715, 05475

Inspection Photos
Location Name: 33-9N33N9W 7SESE
Location ID: 312075



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Weedy debris from the previous inspection doc
#702500227 has not been addressed/resolved.

API #: 067-07146, 09715,
05475

Inspection Photos
Location Name: 33-9N33N9W 7SESE
Location ID: 312075

2/22/24
+37.113478,-107.861763
15° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of additional weedy kochia debris observed on the eastern edge of the disturbance.

API #: 067-07146, 09715,
05475

Inspection Photos
Location Name: 33-9N33N9W 7SESE
Location ID: 312075



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of unused irrigation piping debris observed in the northeast corner of the disturbance.

API #: 067-07146, 09715,
05475

Inspection Photos

Location Name: 33-9N33N9W 7SESE

Location ID: 312075



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of woody and weedy debris observed around the Bondad 33-9
17 well.

API #: 067-07146, 09715,
05475

Inspection Photos
Location Name: 33-9N33N9W 7SESE
Location ID: 312075



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of unused oil and gas equipment observed on location.

API #: 067-07146, 09715,
05475

Inspection Photos
Location Name: 33-9N33N9W 7SESE
Location ID: 312075

2/22/24
+37.113478,-107.861763
91° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area comprised of smooth brome and grama.

API #: 067-07146, 09715,
05475