

# Inspection Photos

Loc: 324789

Operator: WESTERN OPERATING COMPANY

Inspection Date: 2/27/2024

County: Kiowa



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

## Inspection Photos



**Photo 1.** Facing northwest toward the location.



Inspection Photos



**Photo 2.** Facing southeast toward the storage shed adjacent to the tank battery. The tin roof has blown off and it appears more of the shed is close to blowing away.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

## Inspection Photos



**Photo 3.** There was pieces of tin rattling and loose along the vack side of the storage shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

Inspection Photos



**Photo 4.** Inside the shed is various chemical supplies and debris which is an extreme fire hazard that must be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

Inspection Photos



**Photo 5.** Inside the shed is various debris, parts, and trash which is an extreme fire hazard.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

Inspection Photos



**Photo 6.** There is various chemical drums containers and debris which is an extreme fire hazard that must be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

## Inspection Photos



**Photo 7.** Inside the south end of the building is where flowline meter is located. There appears stained soils around the flowline equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

Inspection Photos



**Photo 8.** Facing southeast toward the storage shed adjacent to the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 324789 | Date: 2/27/2024

## Inspection Photos



**Photo 9.** Standing at the wellhead facing east. Sign is posted at wellhead.

