

# Inspection Photos

2/27/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335653

**Inspection Doc:** 696205639

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335653



**Photo 1:** BMPs on the working pad surface have not been maintained; Working pad surface lacks stabilization and tracking BMPs



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335653



February 27, 2024



February 27, 2024

**Photo 2:** Lines at tank has been capped



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

# Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335653



Photo 2: Trash debris removed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources