

Inspection Photos
Location Name: Fonte 33-21
API Number: 125-09192



1. Well sign at CR and access intersection.



2. Rig sign at CR and access intersection.

Inspection Photos
Location Name: Fonte 33-21
API Number: 125-09192



3. Cement truck rigged up to well for cement work.



4. Returns to surface as well is circulated to clean up wellbore for cement work.

Inspection Photos
Location Name: Fonte 33-21
API Number: 125-09192



5. Cement returns to surface as cementing annulus space for repair is completed.



6. Work-over Rig rigged up on well.