

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad

Location #: 324264



Photo # 8027 From entrance to location



Photo # 8028 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad

Location #: 324264



Photo # 8029 Location



Photo # 8030 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad

Location #: 324264



Photo # 8031 Location



Photo # 8032 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM 15-24 (PH15) Pad

Location #: 324264



Photo # 8033 Improperly marked deadman