

Inspection Photos
Location Name: Beebe Draw #1
Location ID: 319335




Photo 1: Gas meter (by self, left of lease road)



Photo 2: Location from entrance

Inspection Photos
Location Name: Beebe Draw #1
Location ID: 319335



Photo 3: Equipment



Photo 4: Unused equipment

Inspection Photos
Location Name: Beebe Draw #1
Location ID: 319335



Photo 5: Tank Battery



Photo 6: Unused Equipment

Inspection Photos
Location Name: Beebe Draw #1
Location ID: 319335




Photo 7: Wellhead, Stained soil



Photo 8: Unused equipment

Inspection Photos
Location Name: Beebe Draw #1
Location ID: 319335




Photo 9: Stained soil



Photo 10: Stained soil