


Inspection Photos
Location Name: McClellan 33-20
Location ID: 328874



Production facility

Inspection Photos
Location Name: McClellan 33-20
Location ID: 328874



Energy & Carbon Management Commission
40.29572, -104.7985, 1432.8m, 115°
01/24/2024 11:31:46

Emergency contact number on 1/24/2024



Energy & Carbon Management Commission
40.29575, -104.7985, 1433.3m, 87°
03/04/2024 10:11:54

Emergency contact number on 3/4/2024

Inspection Photos
Location Name: McClellan 33-20
Location ID: 328874



Debris on 1/24/2024



Debris on 3/4/2024