

Final Reclamation Inspection

February 29th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326090

Inspection Document #: 714000492

La Plata County, CO

Township: NWSE 12 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090



Photo 1. View of the disturbance facing center from the entrance.



Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090



+37 116745 -107 880926
138° SE
2/29/24

Photo 2. Bucket of trash observed at the entrance of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090



Photo 3. View of weedy debris observed in the southern and western edges of the disturbance.

Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090



Photo 4. View of impacted surface material observed at the well head.



Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090



Photo 5. View of unused oil and gas piping observed on location.

Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090



2/29/24
+37.116614,-107.881124
105° E

Photo 6. View of additional unused oil and gas equipment observed in the southeast corner.

Inspection Photos
Location Name: Elmer Dunkel A 1
Location ID: 326090

2/29/24
+37.116519,-107.881072
177° S



Photo 7. View of reference area comprised of smooth brome.