

# Final Reclamation Inspection

February 29th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 333851

Inspection Document #: 714000493

La Plata County, CO

Township: NWNE 12 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bondad 33-10 27  
Location ID: 333851



**Photo 1.** View of the disturbance facing center from the entrance.



API #: 067-07949



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Bondad 33-10 27  
Location ID: 333851



**Photo 2.** View of weedy kochia debris observed in the center and eastern edges of the disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07949



Inspection Photos  
Location Name: Bondad 33-10 27  
Location ID: 333851



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of weedy debris observed in the southern and western edges of the disturbance.

API #: 067-07949



Inspection Photos

Location Name: Bondad 33-10 27

Location ID: 333851



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of the woody debris observed around the well head.

API #: 067-07949



Inspection Photos  
Location Name: Bondad 33-10 27  
Location ID: 333851



2/29/24

+37.122753,-107.881199

331° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** View of the agricultural grass field reference area.

API #: 067-07949