

Final Reclamation Inspection

February 29th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325202

Inspection Document #: 714000498

La Plata County, CO

Township: SWSE 2 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-10 16
Location ID: 325202

2/29/24
+37.128642,-107.899108
283° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the disturbance facing center from the entrance.

API #: 067-05599

Inspection Photos
Location Name: Bondad 33-10 16
Location ID: 325202

2/29/24
+37.128554,-107.899339
222° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the western interim reclamation area facing southwest.

API #: 067-05599

Inspection Photos

Location Name: Bondad 33-10 16

Location ID: 325202



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of storm water CA identified in previous inspection doc #712700654 that has since been addressed/resolved.

API #: 067-05599

Inspection Photos
Location Name: Bondad 33-10 16
Location ID: 325202

2/29/24
+37.128735,-107.899445
268° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of reference area comprised of grama, rabbitbrush and juniper.

API #: 067-05599