

Final Reclamation Inspection

February 29th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306761

Inspection Document #: 714000499

La Plata County, CO

Township: NWNE 11 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Presentacion Medina A 2
Location ID: 306761



Photo 1. View of the disturbance facing center from the entrance.



API #: 067-08713



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Presentacion Medina A 2
Location ID: 306761



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of rill erosion forming in the western interim reclamation area.

API #: 067-08713

Inspection Photos
Location Name: Presentacion Medina A 2
Location ID: 306761



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of rill erosion forming on the eastern side of the access point.

API #: 067-08713

Inspection Photos

Location Name: Presentacion Medina A 2

Location ID: 306761



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of impacted surface material observed at well head.

API #: 067-08713

Inspection Photos

Location Name: Presentacion Medina A 2

Location ID: 306761



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of unused oil and gas fitting equipment observed my the pump jack.

API #: 067-08713

Inspection Photos
Location Name: Presentacion Medina A 2
Location ID: 306761

2/29/24
+37.124659,-107.901100
81° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of reference area comprised of crested wheatgrass, rabbit brush and juniper.

API #: 067-08713