

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403696672

Date Received:

03/05/2024

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

Spill report taken by:

Arauzo, Steven

Spill/Release Point ID:

485745

OPERATOR INFORMATION

Name of Operator: CAERUS PICEANCE LLC	Operator No: 10456	Phone Numbers
Address: 1001 17TH STREET #1600		Phone: (970) 285-2925
City: DENVER State: CO Zip: 80202		Mobile: (970) 640-6919
Contact Person: Blair Rollins		Email: brollins@caerusoilandgas.com

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403626237

Initial Report Date: 12/15/2023 Date of Discovery: 12/14/2023 Spill Type: Recent Spill

Spill/Release Point Location:

QTRQTR NWNW SEC 20 TWP 6S RNG 96W MERIDIAN 6

Latitude: 39.513708 Longitude: -108.139299

Municipality (if within municipal boundaries): County: GARFIELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:

Facility Type: PIPELINE Facility/Location ID No 335161

Spill/Release Point Name: D20 dump line Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Sunny and 45 degrees

Surface Owner: FEE

Other(Specify): Chevron

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The LDAR team was conducting FLIR inspections on the well pad when they identified gas leaking near the separator. The gas was leaking from the gas dump line between the separator and tanks on location. The wells were shut in to control the incident.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
12/14/2023	COGCC	Steven Arauza	720-498-5298	Left a message
12/15/2023	Garfield County	Kirby Wynn	970-625-5905	
12/15/2023	CPW	Taylor Elm	970-986-9767	

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____
Residence or Occupied Structure: _____ Livestock: _____
Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
Enter the Document Number of the Initial Accident Report, Form 22 _____
Was there damage during excavation? _____
Was CO 811 notified prior to excavation? _____

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- The presence of free product or hydrocarbon sheen Surface Water
- The presence of free product or hydrocarbon sheen on Groundwater
- The presence of contaminated soil in contact with Groundwater
- The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
Yes	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>02/23/2024</u>		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>0</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>0</u>	<u>0</u>	<input checked="" type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>30</u>		Width of Impact (feet): <u>15</u>	
Depth of Impact (feet BGS): <u>16</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
<p>On January 18, 2024, an initial release assessment and soil sampling to characterize soil impacts at the point of release (POR) was conducted. After exposing the POR, hand tools were used to collect one soil sample from directly beneath the POR at 5 feet below ground surface (bgs). The soil sample was characterized using visual and olfactory observations, field-screened for volatile organic compounds using a photoionization detector (PID), and submitted for laboratory analysis of all Table 915-1 constituents of concern</p> <p>On February 6, 2024, following the removal of impacted soil at the POR via excavator, an excavation assessment was conducted. Four samples were collected from the sidewalls at 4 to 5 feet bgs and one sample was collected from the base of the excavation at 7.5 feet bgs. Samples were characterized using visual and olfactory observations and field-screened with a PID. Field observations indicated that additional soil removal would be necessary. The samples were submitted for laboratory analysis of total petroleum hydrocarbons (TPH), benzene, toluene, ethylbenzene, xylenes, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene.</p> <p>On February 13, 2024, additional soil excavation and characterization was conducted. Four samples were collected from the sidewalls of the excavation at 10 to 12 feet bgs and one base sample was collected at 16 feet bgs. The samples were submitted for laboratory analysis of an approved reduced analyte list. A total of approximately 700 cubic yards of soil was removed from the excavation and disposed of offsite at Greenleaf Environmental Services.</p> <p>See the attached Report of Work Completed (ROWC) for details.</p>			
Soil/Geology Description:			
<p>Torriorthents-Camborthids-Rock outcrop complex, steep. Lithology at the Location is characterized by high-plasticity inorganic clays with gravel dispersed throughout. Precise depth to groundwater data at the Location is unavailable. The nearest available groundwater measurement is from Division of Water Resources (DWR) well permit 2345968, positioned approximately 0.75 miles south of the site at an elevation of 5,560 feet above mean sea level (AMSL). This well has a static water level of 52.36 feet bgs. The Location sits at an elevation of 5,835 feet AMSL. Although exact depth to groundwater at the location is unknown, it can be inferred to be greater than 300 feet bgs. There is no relevant upgradient groundwater measurement points. The anticipated groundwater flow is towards the east, leading to Parachute Creek and eventually the Colorado River, approximately 6.85 miles southeast of the Location.</p>			
Depth to Groundwater (feet BGS) <u>300</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest Water Well <u>3900</u> None <input type="checkbox"/>		Surface Water <u>2360</u> None <input type="checkbox"/>	

Wetlands 2360 None Springs 5070 None
 Livestock 3300 None Occupied Building 3300 None

Additional Spill Details Not Provided Above:

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached, check all that apply)

Horizontal and Vertical extents of impacts have been delineated.

Documentation of compliance with Table 915-1 is attached.

All E&P Waste has been properly treated or disposed.

Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: _____

SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Caerus requests to utilize CECMC Table 915-1 Footnote 1 to request alternative allowable limits for sodium adsorption ratio (SAR) for the project based on site specific background concentrations collected from native soil within the area. Please refer to the attached report of work completed for site specific background sample locations and results of these efforts.

Based on the information provided in the attached report of work completed and details found within this form, Caerus requests closure and no further action for CECMC Spill/Release Point ID 485745.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Blair Rollins

Title: Environmental Specialist Date: 03/05/2024 Email: brollins@caerusoilandgas.com

COA Type

Description

	Based on review of information presented it appears that no further action is necessary at this time, and ECMC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding ECMC standards or if surface and/or ground water is found to be impacted, then further investigation and/or remediation activities will be required at the site.
1 COA	

Attachment List

Att Doc Num	Name
403696672	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403707640	REMEDATION MEASURES
403707839	FORM 19 SUBMITTED

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)