

FORM
43

Rev
05/21

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

03/04/2024

Document Number:

403707341

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - OGCC Facility ID: 485209 Initial Form 19 or 27 Document number:
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6
County: WELD Field Name:
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 772245 Facility Name: Villani 228631 Facility Type: Domestic Well
Location: QtrQtr: SESE Sec: 25 Twp: 1N Range: 68W Meridian: 6
County Name: WELD Latitude: 40.018110 Longitude: -104.944020

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 117692 Document Name: Size of file in bytes: 31232 File Name: 2023_12_21_Villani 228631 Trip Blank SGS
ECMC.xls
SampleType: Matrix:
Facility ID: 772245 Sample ID: 657072 Sample Name: Villani 228631 Sample Date: 12/21/2023
Collection Point: TB Matrix: WATER Pre Post: Voluntary Post drill
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Accutest Lab Sample ID: DA60898-1

Batch ID: 117691	Document Name: Size of file in bytes: 25600	File Name: 2023_12_21_Villani 228631 SGS ECMC DRO.xls
SampleType: _____		Matrix: _____
Facility ID: 772245	Sample ID: 657071	Sample Name: Villani 228631
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Lab Sample ID: DA60888-1
Batch ID: 117689	Document Name: Size of file in bytes: 76288	File Name: 2023_12_21_Villani 228631 SGS ECMC.xls
SampleType: _____		Matrix: _____
Facility ID: 772245	Sample ID: 657069	Sample Name: Villani 228631
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Lab Sample ID: DA60888-1
Batch ID: 117694	Document Name: Size of file in bytes: 36352	File Name: 2023_12_21_Villani 228631 Isotech NG4 ECMC.xls
SampleType: _____		Matrix: _____
Facility ID: 772245	Sample ID: 657074	Sample Name: Villani 228631
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Lab Sample ID: 905614
Batch ID: 117694	Document Name: Size of file in bytes: 36352	File Name: 2023_12_21_Villani 228631 Isotech NG4 ECMC.xls
SampleType: _____		Matrix: _____
Facility ID: 772245	Sample ID: 657075	Sample Name: Villani 228631
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Lab Sample ID: 905614
Batch ID: 117690	Document Name: Size of file in bytes: 9362	File Name: 2023_12_21_Villani 228631 SGS R ECMC.xlsx
SampleType: _____		Matrix: _____
Facility ID: 772245	Sample ID: 657070	Sample Name: Villani 228631
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Lab Sample ID: DA60888-1
Batch ID: 117693	Document Name: Size of file in bytes: 28160	File Name: 2023_12_21_Villani 228631 Isotech SIW ECMC.xls
SampleType: _____		Matrix: _____
Facility ID: 772245	Sample ID: 657073	Sample Name: Villani 228631
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Lab Sample ID: 904058

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772245	403707367	2023_12_21_Villani_228631_Spigot_Loc.jpg	Photographs	JPG
772245	403707351	2023_12_21_Villani_20231221 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772245	403707369	2023_12_21_Villani_228631_Spigot.jpg	Photographs	JPG
772245	403707365	2023_12_21_Villani_228631_Wellhead_Loc.jpg	Photographs	JPG

772245	403707363	2023_12_21_Villani 20231221 SGS.pdf	Analytical Laboratory Report	PDF
772245	403707364	2023_12_21_Villani_228631 _FS_ECMC.pdf	Field Data Report	PDF
772245	403707349	2023_12_21_Villani 228631 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772245	403707359	2023_12_21_Villani 228631 SGS R.pdf	Analytical Laboratory Report	PDF
772245	403707353	2023_12_21_Villani 228631 Isotech SIW.pdf	Analytical Laboratory Report	PDF
772245	403707357	2023_12_21_Villani 20231221 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772245	403707360	2023_12_21_Villani 20231221 SGS R.pdf	Analytical Laboratory Report	PDF
772245	403707354	2023_12_21_Villani 20231221 Isotech SIW.pdf	Analytical Laboratory Report	PDF
772245	403707366	2023_12_21_Villani_228631 _Wellhead.jpg	Photographs	JPG
772245	403707356	2023_12_21_Villani 228631 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772245	403707362	2023_12_21_Villani 228631 SGS.pdf	Analytical Laboratory Report	PDF
772245	403707372	2023_12_21_Villani_228631 _PrePostPurge.jpg	Photographs	JPG

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	03/05/2024
Total: 1 comment(s)		