

Final Reclamation and Stormwater Inspection

Date: 02/29/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 305587

Inspection Document #: 708200948

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 1. Taken from the start of the former wellhead access road. Undesirable vegetation observed on the access road and former well location. Redline illustrates contouring issues observed at the location, which does not reflect natural topography.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 2. Debris/trash observed on location.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 3. Facing northwest. The former well location requires additional reclamation activities with evidence of undesirable vegetation, areas of bare soils and contouring issues observed during this inspection.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 4. Facing south; see comments in Photo 3.

Inspection Photos
Location Name: N36 Tank
Location ID: 305587



Photo 5. Facing east; see comments in Photo 3.



Photo 6. Degraded straw wattles and stake on location are now considered debris and require removal.