

KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310



Debris



Debris

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Faded and illegible labels**



**Additional information required when replaced**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Debris**




**Debris**

KT Resources LLC  
 Ant Hill Unit 19-44  
 Location ID: 316310



Relief missing rain cap



Overdue calibration

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Location from Northwest corner**



**Location from Southwest corner**

**KT Resources LLC  
Ant Hill Unit 19-44  
Location ID: 316310**



**Location from Southeast corner**



**Location from Northeast corner**