

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/21SWSW

Location ID: 323869

Date: 3/5/2024



Wellhead – Photo #09680



Separator – Photo #09682

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/21SWSW

Location ID: 323869

Date: 3/5/2024



**Tank Battery – Photo #09681**



**Lack of Stabilization – Photo #09683**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/21SWSW

Location ID: 323869

Date: 3/5/2024



Insufficient Administrative Controls – Photo #09688



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09689