


## Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, RMV-66S96W/34NWSW

Location ID: 323967

Date: 3/5/2024



Mar 5, 2024 at 10:03:09  
3555 CR-215  
Parachute CO 81635  
United States



Mar 5, 2024 at 10:04:26  
Parachute CO 81635  
United States

Location Entrance – Photo #09691

Wellhead – Photo #09694

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, RMV-66S96W/34NWSW

Location ID: 323967

Date: 3/5/2024



Separators – Photo #09693



Tank Battery – Photo #09692

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, RMV-66S96W/34NWSW

Location ID: 323967

Date: 3/5/2024



Lack of Stabilization – Photo #09696



Lack of Stabilization/Insufficient Vehicle Tracking BMPs at  
Location Entrance/Exit – Photo #09695