

Daily Operations

Well Name	Surface UWI	Primary Job Typ	Start Date	Summary
UHRICH 11-17	0512323041	Abandon Well - Permanent	11/16/2023	ISITP-0 PSI, ISICP-0 PSI, ISISCP-0 PSI, ROAD RIG AND EQUIPMENT TO LOCATION, SPOT IN AND RIG UP EQUIPMENT, PRES/TEST PUMP LINES AND BOP, N/D TREE, N/U BOP, PRES/TEST CONNECTOR, MIRU A PLUS WIRELINE, RIH AND TAG TOC @6160', POOH, RIH AND JET CUT TBG @6150', POOH, MAKE SURE TBG IS FREE, SECURE WELL, SDFN
UHRICH 11-17	0512323041	Abandon Well - Permanent	11/17/2023	ISITP-0 PSI, ISICP-0 PSI, ISISCP-0 PSI, STAND BACK 37 STANDS AND LAY DOWN REST OF TBG, A PLUS WIRELINE RIH AND SET CIBP @3549.5', POOH, RIH AND SPOT CMT ON TOP, POOH, RIH AND SHOT SQUEEZE HOLES @2451' AND 1951', TIH AND SET CICR @2351', CONDITION HOLE, MIX AND PUMP 10 BBLS OF C/WASH, 5 BBLS OF FRESH WATER AND 190 SKS OF NEAT G CMT @15.8 PPG AND 1.15 YIELD, UNDER DISPLEASE AND SPOT LAST 35 SKS ON TOP OF CICR, POOH TO 1851' AND REVERSE OFF, POOH, SECURE WELL, WINTERIZE EQUIPMENT, SDFN.
UHRICH 11-17	0512323041	Abandon Well - Permanent	11/20/2023	ISICP-0 PSI, ISISCP-0 PSI, PERFORM BUBBLE TEST, NO BUBBLES, WIRELINE RIH AND JET CUT CSG @695', ESTABLISH CIRCULATION AND CONDITION HOLE, N/D TBG EQUIPMENT, BOP AND TBG HEAD, UN LAND CSG, N/U SPOOL, BOP AND 4 1/2 EQUIPMENT, SECURE WELL, WINTERIZE EQUIPMENT, SDFN DUE TO WEATHER CONDITIONS
UHRICH 11-17	0512323041	Abandon Well - Permanent	11/21/2023	ISICP-0 PSI, ISISCP-0 PSI, WAIT ON PIPE HANDLER BEEN REPAIR, L/D 17 JTS OF 4 1/2 CSG, TIH WITH 22 JTS OF 2 3/8 TO 695', ESTABLISH CIRCULATION, MIX AND PUMP 160 SKS OF NEAT G CMT @15.8 PPG AND 1.15 YIELD, POOH, SECURE WELL, SDFN.
UHRICH 11-17	0512323041	Abandon Well - Permanent	11/22/2023	ISISCP-0 PSI, RIH AND TAGGED TOC @373', ESTABLISH CIRCULATION, MIX AND PUMP CMT UP TO SURFACE, POOH, N/D BOP AND SPOOL, TOP OFF WELL, INSTALL SURFACE CAP, TOTAL PUMP 116 SKS OF NEAT G CMT AT 15.8 PPG AND 1.15 YIELD, RIG DOWN PULLING UNIT AND RIG EQUIPMENT, PREPARE FOR RIG MOVE.

Daily Operations

Well Name	Surface UWI	Primary Job Typ	Start Date	Summary
UHRICH 11-17	0512323041	Slot Recovery	12/7/2023	NO PRESSURE/BUBBLE TEST ON THE WELLBORE. NO WELLBORE PRESENT AT SURFACE. PRESSURE/BUBBLE TESTED THE WELL FOR 30 MINUTES ON SURFACE CASING ANNULUS. NO PRESSURE AND NO BUBBLES.
UHRICH 11-17	0512323041	Slot Recovery	2/5/2024	CUT AND CAPPED THE WELL 6 FT BELOW GRADE. HAND THE WELL OVER TO RECLAMATION.