# Daily Operations

| Well Name | Surface UWI | Primary Job Typ | Start Date | Summary |
|---|---|---|---|---|
| MOSER H34-15 | 0512323196 | PLUG AND ABANDON | 8/12/2020 | RRTL HSM SPOT EQUIPMENT<br>MIRU<br>LAY & TEST HARDLINE W/BOP & TIW = GOOD<br>IWP 775/785 60 SURF<br>TAKE GAS SAMPLE & PERFORM BRHD TEST<br>KILL WELL & CIRC<br>NDWH NUBOP TEST RING = GOOD<br>TOH S/B 74 LD 30<br>SWI SDFN RCTT |
| MOSER H34-15 | 0512323196 | PLUG AND ABANDON | 8/13/2020 | RCTL HSM IWP VAC/VAC 11 SURF<br>LD 113 JNTS<br>HSM W/WL & R/U<br>SET CIBP @ 6822' D/B 2 SX<br>LOAD HOLE TEST TO 500# = GOOD<br>SET CIBP @ 4207' D/B 2 SX<br>PERF CSG @ 2500' BK DOWN PERF<br>PERF CSG @ 2000' TOOK GAS KICK<br>RIH CICR STACK OUT ON HEAVY MUD @ 1690' POOH<br>TIH 74 JNTS & CIRC HOLE CLEAN<br>RIH SET CICR @ 2400' R/D WL<br>TIH 72 JNTS + 28' OF SUBS STING INTO CICR<br>HSM W/CEMENTERS & R/U<br>BK CIRC P/10 BBLS MUD FLUSH P/5 BBLS FW SPACER P/180 SX GAS CHECK (21.6 MIX, 37.5 SLURRY, YIELD 1.17, 7.0 PH, 15.8 PPG)<br>DISP 3 BBLS FW STING OUT DISP 4 BBLS FW & BALANCE 30 SX ON TOP OF CICR<br>TOH S/B 36 JNTS & REV CIRC LD 36 JNTS<br>SWI SDFN RCTT |
| MOSER H34-15 | 0512323196 | PLUG AND ABANDON | 8/14/2020 | RCTL HSM W/WL IWP 5 CSG 48 SURF<br>R/U WL RIH CUT CSG @ 1205' R/D WL<br>BK CIRC CONDITION HOLE C/O FOR CSG<br>NDWH UNLND CSG NUBOP<br>LD 28 JNTS CSG<br>LOAD HOLE<br>SWI SDFWE RCTT |
| MOSER H34-15 | 0512323196 | PLUG AND ABANDON | 8/17/2020 | RCTL HSM IWP SLIGHT BLOW SURF<br>BOP LEAKED OIL OVER WEEKEND OUT OF PISTON SEAL ON BLIND RAMS<br>NDBOP REPLACE WITH TESTED BOP NUBOP<br>PERFORM 30 MIN SHUT IN & FLOW CHECK = NO FLOW/BUBBLES<br>TIH 36 JNTS LD 8 JNTS EOT 909'<br>HSM W/CEMENTERS & R/U BK CIRC<br>P/403 SX G TO SURF R/D CEMENTERS<br>LD 28 JNTS<br>NDBOP CAP WELL & SWI<br>CLEAN TANKS R/O PUMP & TANKS<br>RDMO SDFN RCTT |

## Daily Operations

| Well Name | Surface UWI | Primary Job Typ | Start Date | Summary |
|---|---|---|---|---|
| MOSER H34-15 | 0512323196 | Slot Recovery | 12/6/2023 | PRESSURE/BUBBLE TESTED THE WELL FOR 30 MINUTES ON WELLBORE. NO PRESSURE AND NO BUBBLES.<br><br>PRESSURE/BUBBLE TESTED THE WELL FOR 30 MINUTES ON SURFACE CASING ANNULUS. NO PRESSURE AND NO BUBBLES. |
| MOSER H34-15 | 0512323196 | Slot Recovery | 2/5/2024 | CUT AND CAPPED THE WELL 6 FT BELOW GRADE. HAND THE WELL OVER TO RECLAMATION. |