

# Final Reclamation Inspection

March 6th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 326452

Inspection Document #: 714000509

La Plata County, CO

Township: SENW 3 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Argenta 33-10 3-1  
Location ID: 326452



3/6/24  
+37.135898,-107.923689  
265° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of the disturbance facing center from the entrance.

API #: 067-08128

Inspection Photos  
Location Name: Argenta 33-10 3-1  
Location ID: 326452



**Photo 2.** View of the northern interim reclamation area facing northwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08128

Inspection Photos  
Location Name: Argenta 33-10 3-1  
Location ID: 326452



3/6/24  
+37.136160,-107.923853  
249° W

**Photo 3.** View of weedy russian thistle debris observed around the well head.

Inspection Photos  
Location Name: Argenta 33-10 3-1  
Location ID: 326452



**Photo 4.** View of unused oil and gas equipment stored on location.

Inspection Photos

Location Name: Argenta 33-10 3-1

Location ID: 326452



**Photo 5.** View of gully erosion forming on the western edge of the disturbance.

Inspection Photos  
Location Name: Argenta 33-10 3-1  
Location ID: 326452



**Photo 6.** View of rutting on location at the access point. Additional stabilization is needed in this area to minimize site degradation.

Inspection Photos  
Location Name: Argenta 33-10 3-1  
Location ID: 326452



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 7.** View of reference area comprised of indian rice grass, rabbit brush, sagebrush and juniper.

API #: 067-08128