

# Final Reclamation Inspection

March 6th, 2024

Operator: Robert L. Bayless Producer LLC - 6720

Location ID: 325387

Inspection Document #: 714000510

La Plata County, CO

Township: SWNE 3 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Indian Springs 2  
Location ID: 326387

3/6/24  
+37.135890,-107.918369  
146° SE



**Photo 1.** View of the disturbance facing center from the entrance.

Inspection Photos  
Location Name: Indian Springs 2  
Location ID: 326387





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the eastern interim reclamation area facing southeast.

API #: 067-06289

Inspection Photos  
Location Name: Indian Springs 2  
Location ID: 326387



**Photo 3.** View of gully erosion forming on the western edge of the disturbance at the access point. Erosion is tunneling through exterior berm and causing additional erosion and sediment transport off of the location.



Inspection Photos  
Location Name: Indian Springs 2  
Location ID: 326387



Photo 4. View of weedy kochia debris encroaching on tanks.



Inspection Photos  
Location Name: Indian Springs 2  
Location ID: 326387



**Photo 5.** View of erosion forming along the access road where additional stormwater BMPs are needed.



Inspection Photos  
Location Name: Indian Springs 2  
Location ID: 326387



3/6/24  
+37.135205 -107.918194  
201° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference area comprised of poa secunda, snake weed, mountain mahogany, gambel oak and juniper.

API #: 067-06289