

# Inspection Photos

3/06/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335743

**Inspection Doc:** 696205645

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



**Photo 1:** Photos 1-2 taken from the northeast end of the Location. Photos provides an overview of the Location from south, southwest, northwest to north.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



**Photo 3:** Photos taken from the working pad surface. Photos examples showing BMPs on the working pad surface have not been installed or maintained; Working pad surface lacks stabilization and tracking BMPs



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



**Photo 4:** Photo example showing stormwater ponding on the WPS and facilitated in destabilization of the WPS, and has resulted in ponding around production equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



**Photo 5:** Photos examples showing areas of the working pad surface where additional work to stabilize the pad has been performed. BMPs and work to stabilize the remaining WPS, and to minimize erosion, degradation and sediment transport remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



March 6, 2024



March 6, 2024

**Photo 6:** Additional BMPs to allow for proper stormwater discharge implemented on the east end of the Location, and access road to the north.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



**Photo 7:** Fencing at wells in disrepair.