

Inspection Photos

3/06/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742

Inspection Doc: 696205651

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 1: Photos 1-2 taken from the east end of the well pad. Photos provide an overview of the location from northwest, north, northeast to southeast.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 1: See comments under photo 1. Photo right also example showing areas of the southern well pad not reasonable needed for production.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 3: Photos taken from the southend of the well pad, facing northeast and east. Photos examples showing areas on the south end of the well pad Location not reasonably needed for production. Areas require reclamation pursuant to 1003 rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 4: Google Earth aerial image. Red polygon represent approximate areas of the well pad not reasonable necessary for production activities.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 5: Photo shows fence at the wells is in disrepair.

Open

50



March 6, 2024



March 6, 2024



March 6, 2024

Photo 6: Photos taken from the east end of the Location. Photo shows unused pipe equipment; pipe disconnected and broken along sections.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742



Photo 7: Photos taken from the east end of the Location. Photos examples showing various trash debris observed along unused pipe.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335742




Photo 8: Wildlife mortality observed at the tank battery facility.