

Inspection Photos

3/06/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788

Inspection Doc: 696205653

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos also show BMPs to stabilize the working pad surface have been maintained.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 3: Photo example showing fence at wells is in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 4: Photos taken from the slopes behind the battery facility on the north end of the Location. Photos show BMPs to minimize erosion and degradation at the slopes remain missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



March 6, 2024

Photo 5: See comments under photo 4. Photo also shows sediment deposition due to erosion at the unstabilized slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources