

# Inspection Photos

3/06/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335777

**Inspection Doc:** 696205655

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



March 6, 2024



March 6, 2024

**Photo 1:** Photos taken from the Location entrance on the east end of the Location. Photos provide an overview of the Location from from southwest to west. Photos also show BMPs to stabilize the working pad, as well as to minimize erosion, degradation and sediment transport (tracking) remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



**Photo 2:** BMPs to stabilize the working pad, as well as to minimize erosion, degradation and sediment transport (tracking) remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



**Photo 3:** Photos taken from the southeast end of the Location, facing southwest and west. Photos show stormwater and erosion control BMPs to manage runoff in a manner that minimizes erosion and degradation at the east end of the Location remains missing or insufficient; erosion degradation has persisted.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



**Photo 4:** Photo shows fencing at the wells remains in disrepair.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



**Photo 5:** Marker at anchor on the southwest end of the Location in disrepair.