

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**Erosion and sediment migration**

**Erosion and sediment migration**

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**Erosion and sediment migration**

**Erosion and sediment migration**

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**As signs are replaced additional information is required**



**Debris**

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**Bradenhead?**




**Erosion and sediment migration**

KT Resources LLC  
 WRD Federal 30-24  
 Location ID: 316148



Relief riser missing rain cap



Calibration overdue

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**Erosion and sediment migration**



**As signs are replaced additional information is required**

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**Location from Northwest corner**

**Location from Northeast corner**

**KT Resources LLC  
WRD Federal 30-24  
Location ID: 316148**



**Location from Southeast corner**



**Location from Southwest corner**