

**KT Resources LLC  
Ant Hill Unit 29-11  
Location ID: 316309**



**Lack of maintenance with previous weed growth**




**As signs are replaced additional information is required**

KT Resources LLC  
Ant Hill Unit 29-11  
Location ID: 316309




Previous year lack of weed maintenance



Previous operator emergency number

KT Resources LLC  
 Ant Hill Unit 29-11  
 Location ID: 316309



Gas meter calibration display

Calibration overdue

**KT Resources LLC  
Ant Hill Unit 29-11  
Location ID: 316309**



**Location from Southwest corner**



**Location from Northwest corner**

**KT Resources LLC  
Ant Hill Unit 29-11  
Location ID: 316309**



**Location from Northeast corner**



**Location from Southeast corner**