

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/34NWSW

Location ID: 335111

Date: 3/5/2024



Mar 5, 2024 at 10:03:09
3555 CR-215
Parachute CO 81635
United States



Mar 5, 2024 at 10:06:40
3555 CR-215
Parachute CO 81635
United States

Location Entrance – Photo #09691



Wellheads – Photo #09697

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/34NWSW

Location ID: 335111

Date: 3/5/2024



Weathered Wellhead Sign – Photo #09698


Weathered Wellhead Sign – Photo #09699

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/34NWSW

Location ID: 335111

Date: 3/5/2024



Weathered Wellhead Sign – Photo #09700



Lack of Stabilization – Photo #09696

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/34NWSW

Location ID: 335111

Date: 3/5/2024



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs at
Location Entrance/Exit – Photo #09695**