

**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**



**When replaced additional information is required**



**Erosion and sediment migration**



**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**

Evl. 5799' Rio Blanco ROC 503 Mar 6, 2024 at 2:17:47 PM

**EMPACT ANALYTICAL SYSTEMS INC.**  
 365 SOUTH MAIN  
 BRIGHTON, CO 80601  
 303-637-0150 www.empactanalytical.com

Meter S/N  
15828462  
C-55438

Station Name AHU 36-11 BD  
 Station No. 120275595 Producer 31 OP  
 Sec 36 Township 2N Range 97W  
 Diff 250" Temp Range 0-150 Tube Size 2.067  
 Static 200" Absolute 11.84 psi

Date	Orifice Plate Size	Meter Test Date	Sample Date
6W 3-22-18	1.375	3-22-18	3-22-18
KB 8-22-18	1.375	8-22-18	8-22-18
KB 2-27-19	1.375	2-27-19	2-18-19
0.7941 9-11-19	1.375	9-11-19	9-11-19
2-9-22	1.375	2-9-22	

KB

**Calibration overdue**

Evl. 5783' Rio Blanco ROC 503 Mar 6, 2024 at 2:18:21 PM

**EMPACT ANALYTICAL SYSTEMS INC.**  
 365 SOUTH MAIN  
 BRIGHTON, CO 80601  
 303-637-0150 www.empactanalytical.com

Meter S/N  
15828462  
C-55438

Station Name AHU 36-11  
 Station No. 120275594 Producer 31 OP  
 Sec 36 Township 2N Range 97W  
 Diff 250" Temp Range 0-150 Tube Size 2.067  
 Static 200" Absolute 11.91 psi

Date	Orifice Plate Size	Meter Test Date	Sample Date
6W 3-22-18	1.000	3-22-18	3-22-18
KB 9-19-18	1.000	9-19-18	9-19-18
KB 4-17-19	1.000	4-17-19	4-17-19
0.8030 9-11-19	1.000	9-11-19	9-11-19
2-9-22	1.000	2-9-22	

KB

**Calibration overdue**



**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**



**Missing riser rain protection**



**Unable to verify bird protection**

KT Resources LLC  
Ant Hill Unit-62N97W 36NWNW  
Location ID: 336462



When replaced additional information is required



When replaced additional information is required



**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**




**Lack of compaction and stabilization**



**Open end load line. Valve left open**



KT Resources LLC  
Ant Hill Unit-62N97W 36NWNW  
Location ID: 336462



Oily waste and stained soil



Oily waste and stained soil





**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**



**Oily waste and stained soil**



**Oily waste and stained soil**



**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**



**Possible seepage**



**Erosion and sediment migration**



**KT Resources LLC**  
**Ant Hill Unit-62N97W 36NWNW**  
**Location ID: 336462**



**Location from Southeast corner**



**Location from Northwest corner**