

# Final Reclamation Inspection

March 6th, 2024

Operator: Simcoe LLC - 10749

Location ID: 312080

Inspection Document #: 714000516

La Plata County, CO

Township: SWNW 14 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Thomas Jacquez A 1  
Location ID: 312080



Photo 1. View of the disturbance facing center from the entrance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07463



Inspection Photos  
Location Name: Thomas Jacquez A 1  
Location ID: 312080



3/6/24  
+37.106251,-107.907982  
327° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the northern interim reclamation area facing northwest.

API #: 067-07463







Inspection Photos  
Location Name: Thomas Jacquez A 1  
Location ID:312080



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Impacted surface material observed at the well head.

API #: 067-07463



Inspection Photos  
Location Name: Thomas Jacquez A 1  
Location ID: 312080



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of grama, crested wheatgrass and juniper.

API #: 067-07463