

# Final Reclamation Inspection

March 6th, 2024

Operator: Benson Montin and Greer Drilling Corporation - 7650

Location ID: 325299

Inspection Document #: 714000520

La Plata County, CO

Township: NWNW 10 33N 10W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: DL Gould Flume Canyon 2


Location ID: 325299



Inspection Photos

Location Name: DL Gould Flume Canyon 2

Location ID: 325299




**Photo 2.** Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.


Inspection Photos

Location Name: DL Gould Flume Canyon 2

Location ID: 325299



3/6/24  
+37.122400,-107.926566  
165° S



3/6/24  
+37.122400,-107.926566  
248° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources


**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: Sparse vegetation at the well pad.

API #: 067-06117

Inspection Photos

Location Name: DL Gould Flume Canyon 2

Location ID: 325299



**Photo 4.** View of rill and gully erosion forming on the northwest portion of the disturbance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06117

Inspection Photos

Location Name: DL Gould Flume Canyon 2

Location ID: 325299



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** View of reference area comprised of smooth brome, rabbit brush, sagebrush and juniper.

API #: 067-06117