

Final Reclamation Inspection

March 6th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326359

Inspection Document #: 714000522

La Plata County, CO

Township: SENE 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta 3R
Location ID: 326359



Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos

Location Name: La Posta 3R

Location ID: 326359



Photo 2. View of gully erosion persisting along the access road and stormwater BMPs that are inadequate.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07195

Inspection Photos
Location Name: La Posta 3R
Location ID: 326359



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of additional rill erosion persisting in the western interim reclamation area.

API #: 067-07195

Inspection Photos
Location Name: La Posta 3R
Location ID: 326359



3/6/24
+37.135178,-107.952230
48° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the eastern interim reclamation area facing northeast.

API #: 067-07195