

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: ANDERSON TRUST C UNIT PAD 2

Loc ID: 322848

Inspection: 714300044



Exhibit A

CA: Fencing surrounding the excavation is beginning to sag and requires maintenance. Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.

CA Resolution: Operator has appropriately repaired the fencing around the excavation to comply with Rule 913.b.(5).B.i.