

Final Reclamation Inspection

March 6th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326631

Inspection Document #: 714000532

La Plata County, CO

Township: NENW 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



3/6/24
+37.144686,-107.954697
149° SE



3/6/24
37.137095,-107.957423
115° SE

Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631

3/6/24
+37.140755, -107.951064
79° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the northern interim reclamation area facing east.

API #: 067-08489

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Storm water CA identified in the previous inspection doc #714000147 has been addressed/resolved.

API #: 067-08489

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



3/6/24
+37.137095,-107.957423
343° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of unused oil and gas piping equipment observed on location.

API #: 067-08489

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Rutting observed on the eastern side of the disturbance. Additional stabilization is needed to minimize site degradation.

API #: 067-08489

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of smooth brome, sage brush and juniper.

API #: 067-08489