

**Operator: 8 North**

**Location Name: Silverback 36-A Pad**

**Loc ID: 443555**

**Inspection: 696306065**



Exhibit A



Exhibit B



Exhibit C



Exhibit D

**CA:** Stained Soil at both Gas Engines, see photos. For localized stained soils or oily waste - Properly dispose of oily waste in accordance with 905.e.

**CA Resolution:** Oily waste has been disposed of to comply with Rule 905.e.

**CA:** Unmarked Risers at Gas Meter House on East side of Location. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

**CA Resolution:** Risers have marked to comply with Rule 1105.