

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 3/7/2024



Location Entrance – Photo #09722



Wellheads – Photo #09723

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 3/7/2024



Separators – Photo #09727



Tank Battery – Photo #09725

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 3/7/2024



Weathered Battery Sign – Photo #09728

Open-Ended Load Line – Photo #09726

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 3/7/2024



Unprotected Soil Stockpile – Photo #09730

Unprotected Soil Stockpile – Photo #09731

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 3/7/2024



Lack of Stabilization – Photo #09732

Lack of Stabilization – Photo #09733

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SESE

Location ID: 334849

Date: 3/7/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09734**

Insufficient Administrative BMP – Photo #09735