

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/34SESW

Location ID: 324003

Date: 3/7/2024



Location Entrance – Photo #09763



Wellhead – Photo #09764

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/34SESW

Location ID: 324003

Date: 3/7/2024



Separator – Photo #09765



Tank Battery – Photo #09766

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/34SESW

Location ID: 324003

Date: 3/7/2024



**Weathered Battery Sign – Photo #09768**



**Open-Ended Load Line – Photo #09767**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/34SESW

Location ID: 324003

Date: 3/7/2024



Lack of Stabilization – Photo #09769



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09770