

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Mar 11, 2024 at 1:45:07 PM
CO



Mar 11, 2024 at 2:01:10 PM
CO

Photo # 9277 From entrance to location

Photo # 9278 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 9279 Location



Photo # 9280 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 9281 Location



Photo # 9282 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 9283 Unused equipment/ECD disconnected

