

Inspection Photos

Loc: 334111

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 3/11/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road which is rutted and not maintained.



Inspection Photos



Photo 2. Facing west along the access road which is rutted and not maintained.



Inspection Photos



Photo 3. Facing north at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334111 | Date: 3/11/2024