

# Inspection Photos

Loc: 309050

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 3/11/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast toward the access road. The gate has fallen off the hinges and needs maintenance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309050 | Date: 3/11/2024



## Inspection Photos



**Photo 2.** Facing northeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:309050 | Date: 3/11/2024