

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



1. Location sign at gated entrance.



2. Steel built 12' X 12" building.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



3. Steel built 25' X 35" compressor building.



4. Compressor.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



5. Oil tank in secondary containment.



6. Buried steel sump tank outside compressor building.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



7. Fiberglass tank in secondary containment.



8. Wash out.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



9. Separation equipment sheds and separators.



10. Plastic tank in secondary containment.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



11. Steel built 25' X 30" compressor building.



12. Compressor.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



13. Oil tank in secondary containment.



14. Buried sump tank outside compressor building.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



15. Location overview.



16. Location overview.

Inspection Photos
Location Name: Republican Compressor Station
API Number: 412141



17. Location overview.



18. Location overview.