

# Final Reclamation and Stormwater Inspection

Date: 03/11/2024

Operator: NOBLE ENERGY INC - 100322

Location ID: 415637

Inspection Document #: 708200984

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: 70 Ranch USX BB 35-02  
Location ID: 415637



**Photo 1.** Undesirable vegetation and areas of exposed soils observed along the access road.



Inspection Photos  
Location Name: 70 Ranch USX BB 35-02  
Location ID: 415637



3/11/24, 11:19 AM  
258° W  
ECMC

**Photo 2.** Undesirable vegetation and areas of exposed soils observed along the access road.

Inspection Photos  
Location Name: 70 Ranch USX BB 35-02  
Location ID: 415637



**Photo 3.** East side of former location. The former location does not appear to be progressing towards Rule 1004 standards and regulations with bare soil and undesirable vegetation observed.



Inspection Photos  
Location Name: 70 Ranch USX BB 35-02  
Location ID: 415637



**Photo 4.** South side of former location; see comments in Photo 3.

Inspection Photos  
Location Name: 70 Ranch USX BB 35-02  
Location ID: 415637



**Photo 5.** North side of former location; see comments in Photo 3.



Inspection Photos  
Location Name: 70 Ranch USX BB 35-02  
Location ID: 415637



**Photo 6.** Reference area photo taken south of the location; desirable species observed include - switchgrass, prairie sandreed, sand bluestem etc.